

DAFTAR GAMBAR

Gambar 2.1 Diagram Fasa Fe-Fe ₃ C (http://eprints.unpam.ac.id/6313/3/BAB II.pdf)	5
Gambar 2.2 Isothermal Transformation diagram	6
Gambar 2.3 Continuous Cooling Transformation Diagram.....	8
Gambar 2.4 tabel standart kekerasan (refrensi titi uji keras da lebar HAZ ITS)	10
Gambar 2.5 tabel acuan memilih timbangan (refrensi titi uji keras da lebar HAZ ITS)	11
Gambar 3.1 Diagram alir	13
Gambar 3.2 Baja Profil	14
Gambar 3.3 Hardening Furnace	14
Gambar 3.4 Cairan.....	15
Gambar 3.5 Oli.....	15
Gambar 3.6 Air	16
Gambar 3.7 Mikroskop.....	16
Gambar 3.8 Alat Uji Impak.....	17
Gambar 3.9 Amplas	17
Gambar 3.10 autosol	18
Gambar 3.11 Mesin Gergaji Potong.....	18
Gambar 4.1 diagram kekerasan	23
Gambar 4.2 diagram fasa ferrit.....	26
Gambar 4.3 diagram fasa perlit	26
Gambar 4.4 perhitungan fasa.....	29
Gambar 4.5 Struktur Mikro.....	29

DAFTAR TABEL

Tabel 4.1 Hasil pemanasan specimen.....	21
Tabel 4.2 Hasil pengujian kekerasan	22
Tabel 4.3 Presentase struktur mikro	24