

LAMPIRAN

Analisa Laju Korosi Bahan Bakar Bensin Dan Solar Pada Plat Tangki Mobil Dengan Variasi Arus 8v, 10v Dan 12v

ORIGINALITY REPORT

9 %	9 %	0 %	1 %
SIMILARITY INDEX	INTERNET SOURCES	PUBLICATIONS	STUDENT PAPERS


PRIMARY SOURCES

1	dokumen.tech Internet Source	1 %
2	journal.ipb.ac.id Internet Source	1 %
3	journal.ppns.ac.id Internet Source	1 %
4	jurnal.batan.go.id Internet Source	1 %
5	docplayer.info Internet Source	1 %
6	publikasiilmiah.ums.ac.id Internet Source	1 %
7	media.ihram.asia Internet Source	1 %
8	text-id.123dok.com Internet Source	1 %
9	repository.its.ac.id Internet Source	<1 %

Exclude quotes Off

Exclude matches Off

Exclude bibliography Off



Gambar.Rangkaian Kipas pendingin dan travo multi arus



Gambar.Accu 12v pengujian korosi



Gambar Rangkain Alat Uji



Gambar Avometer Alat Uji



Gambar Pengukuran Alat Uji 5cm x 5cm



Gambar Plat Uji Yang Sudah Dipotong



Gambar Perendaman Plat



Gambar hasil Pengkorosian



A



B

Gambar uji SEM+EDS